



(ASSESSMENT CENTER BOQ FORM)

ASSESSORS EMAIL ADDRESS: domainoperations2@gmail.com

DATE: 24/05/2022

VEHICLE LOCATION : COTTCO PREMISES HARARE

VEHICLE DETAILS:

REG NO : AES 4531

MAKE : ISUZU

MODEL : KB 250

YEAR : 2017

CHASSIS # : ACVLRRAR9H4004573

PARTS APPROVED FOR REPLACEMENT:

Click On Add Row To Add Parts
BONNET
HEADLAMPS X2
FRONT BUMPER
GRILLE
MAIN GRILLE
BOOTOM GRILLE
SUPPORT PANEL
GRILLE BADGE
RADAITOR
INTERCOOLER
AIR CON RADIATOR
REGAS
COLANT
FAN BLADE
FAN VISCOUSE
FAN COWING
AIR CLEANER HOUSING
AIR FILTER
RIGHT FRONT FENDER
WINDSCREEN
AIR DUCTS
BUMPER SLIDES
BONNET CATCH
WASHER BOTTLE
STEERINGRING FLUID BOTTLE
BRAKE FLUID BOTTLE
INNER BUMPER FRAME
RIGHT INNER FENDER
TOP RADIATOR COVER
TIMING BELT
TIMING BELT PULLY

PANELS APPROVED FOR REPAIR:

2

Click On Add Row To Add Parts
LEFT FRONT FENDER
RIGHT FRONT DOOR
CUT AND JOIN SUPPORT PANEL
CUT AND JOIN RIGHT INNER FENDER

NUMBER OF PANELS APPROVED FOR PAINTWORK: 8

SPECIAL CONDITIONS (WARRANTY) AFTERMARKET PARTS ACCEPTABLE (OUT OF WARRANTY)

UPLOAD VEHICLE IMAGES:



